



Light Damage Charges Schedule

			CARS				VANS		
Area	Element	Type and Condition	Small	Medium	Intermediate	Large	Premium	Small Van	Van
Front	Badge	Broken/Damaged/Missing	56	70	98	72	158	65	49
	Bonnet	Scratch/Scuff <75mm Paint Damage	244	297	320	326	340	268	235
		Scratch/Scuff - Medium 75-150mm	479	550	595	596	541	541	575
		Scratch/Scuff - Large 150mm+	652	738	802	803	662	751	856
		Dent - Small 25-75mm	282	335	358	364	378	307	274
		Dent - Medium 75-150mm	556	627	672	673	618	618	652
		Dent - Large 150mm+	768	853	918	919	777	866	971
	Bumper Moulding	Broken/Damaged/Missing	167	214	170	235	211	43	100
	Bumper skirt	Broken/Damaged/Missing/Scuffed	113	103	65	88	67	77	79
	Front Bumper	Scratch/Scuff <75mm Paint Damage	262	273	260	258	228	303	212
		Scratch/Scuff - Medium 75-150mm	345	365	351	348	314	408	289
		Scratch/Scuff - Large 150mm+	345	365	351	348	304	408	479
		Dent - Small 25-75mm	300	312	298	296	267	341	250
		Dent - Medium 75-150mm	422	442	428	425	391	485	366
		Dent - Large 150mm+	460	481	467	464	420	523	595
	Fog Light (Right/Left)	Broken/Damaged/Missing	54	109	98	104		128	80
	Front Grille	Broken/Damaged/Missing	55	164	175	172	337	137	117
	Indicator (Right/Left)	Broken/Damaged/Missing	25	16	19	15	27	28	16
	Front Skirt (Right/Left)	Broken/Damaged/Missing	113	103	66	88	67	78	79
	Tow Eye Cover	Broken/Damaged/Missing	125	127	120	105	38	24	25
Wiper Arm	Broken/Damaged/Missing	44	60	70	60	78	49	71	
Wiper Blades	Broken/Damaged/Missing	36	23	22	28	43	30	28	
Number Plate	Broken/Damaged/Missing	25	25	25	25	25	25	25	
Wind Screen	Glass chip 5-10mm	35	35	35	35	35	35	35	
Side (Right/Left)	Door (Front/Rear)	Scratch/Scuff <75mm Paint Damage	249	243	254	245	221	264	291
		Scratch/Scuff - Medium 75-150mm	487	470	499	480	383	533	651
		Scratch/Scuff - Large 150mm+	664	641	684	662	499	742	949
		Dent - Small 25-75mm	287	281	293	283	259	302	329
		Dent - Medium 75-150mm	564	547	576	557	460	610	728
		Dent - Large 150mm+	780	756	800	778	614	857	1065
	Door Handle (Front/Rear)	Broken/Damaged	128	163	155	189	57	51	37
		Scratch/Scuff <75mm Paint Damage	128	123	130	118	83	51	37
	Door Seal (Front/Rear)	Broken/Damaged/Missing	146	73	77	74	132	87	64
	Front Wing	Scratch/Scuff <75mm Paint Damage	167	169	188	170	174	180	183
		Scratch/Scuff - Medium 75-150mm	365	363	403	370	314	408	492
		Scratch/Scuff - Large 150mm+	516	510	567	529	427	591	757
		Dent - Small 25-75mm	205	208	226	208	212	218	221
		Dent - Medium 75-150mm	442	440	480	447	391	485	569
		Dent - Large 150mm+	631	625	682	644	542	707	872
	Fuel Flap	Broken/Damaged	198	174	185	149	175	162	175
		Scratch/Scuff <75mm Paint Damage	129	126	132	120	92	128	129
	Side Indicator Repeater	Broken/Damaged	29	17	21	23	27	20	16
	Door Mirror Glass	Broken/Damaged/Missing	42	55	67	89	165	39	31
	Mirror Housing	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65	65
		Broken/Damaged/Missing	130	203	218	248	296	153	151
	Moulding (Front/Rear)	Broken/Damaged/Missing	153	109	89	185	155	77	43
	Rear Wing	Scratch/Scuff <75mm Paint Damage	223	213	214	249	220	251	394
		Scratch/Scuff - Medium 75-150mm	444	422	445	476	376	515	810
		Scratch/Scuff - Large 150mm+	615	580	615	651	490	724	1136
		Dent - Small 25-75mm	262	251	253	288	259	290	432
		Dent - Medium 75-150mm	521	499	522	553	453	592	887
		Dent - Large 150mm+	730	696	731	767	606	839	1251
Pillar A	Scratch/Scuff <75mm Paint Damage	154	165	166	167	148	172	185	
	Scratch/Scuff - Medium 75-150mm	217	227	233	230	176	245	241	
	Scratch/Scuff - Large 150mm+	236	246	254	254	179	270	250	
	Dent - Small 25-75mm	193	203	204	206	186	210	224	



Light Damage Charges Schedule

Area	Element	Type and Condition	CARS				VANS			
			Small	Medium	Intermediate	Large	Premium	Small Van	Van	
Pillar B		Dent - Medium 75-150mm	294	304	310	307	253	322	318	
		Dent - Large 150mm+	352	361	369	369	294	385	366	
		Scratch/Scuff <75mm Paint Damage	166	182	178	182	181	184	208	
		Scratch/Scuff - Medium 75-150mm	235	254	254	252	212	260	291	
		Scratch/Scuff - Large 150mm+	255	278	279	274	215	289	327	
		Dent - Small 25-75mm	204	220	217	221	220	222	246	
		Dent - Medium 75-150mm	312	331	331	329	289	337	368	
Pillar C		Dent - Large 150mm+	371	393	394	390	330	404	442	
		Scratch/Scuff <75mm Paint Damage						156	177	
		Scratch/Scuff - Medium 75-150mm						156	245	
		Scratch/Scuff - Large 150mm+						156	282	
		Dent - Small 25-75mm						194	216	
		Dent - Medium 75-150mm						233	322	
Pillar D		Dent - Large 150mm+						271	397	
		Scratch/Scuff <75mm Paint Damage						140	150	
		Scratch/Scuff - Medium 75-150mm						140	181	
		Scratch/Scuff - Large 150mm+						140	190	
		Dent - Small 25-75mm						179	189	
		Dent - Medium 75-150mm						217	258	
Sill		Dent - Large 150mm+						256	305	
		Scratch/Scuff <75mm Paint Damage	167	169	172	176	176	172	168	
		Scratch/Scuff - Medium 75-150mm	237	235	241	245	236	243	235	
		Scratch/Scuff - Large 150mm+	258	256	265	270	238	268	256	
		Dent - Small 25-75mm	206	207	210	215	214	210	207	
		Dent - Medium 75-150mm	314	312	318	322	313	320	312	
Underside Protection		Dent - Large 150mm+	374	372	381	385	353	384	372	
		Broken/Damaged/Missing	68	106	106	75	73	88	78	
	Wheel Trim (Front/Rear)	Broken/Damaged	31	45	42	38		30	32	
	WingTrims	Missing	92	87	112	95	122	41	10	
	Wheel Arch (Front/Rear)		Scratch/Scuff <75mm Paint Damage		44	171	31	199		
			Scratch/Scuff - Medium 75-150mm		44	171	31	199		
		Scratch/Scuff - Large 150mm+		44	171	31	199			
		Dent - Small 25-75mm		44	210	31	238			
		Dent - Medium 75-150mm		44	248	31	276			
		Dent - Large 150mm+		44	287	31	315			
Door Glass (Front/Rear)	Glass chip 5-10mm	35	35	35	35	35	35	35		
Alloy/Steel Wheel (Front/Rear)	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65	65		
Left Side Rear Panel		Scratch/Scuff <75mm Paint Damage						251	394	
		Scratch/Scuff - Medium 75-150mm						515	810	
		Scratch/Scuff - Large 150mm+						724	1136	
		Dent - Small 25-75mm						290	432	
		Dent - Medium 75-150mm						592	887	
		Dent - Large 150mm+						839	1251	
Right Side Rear Panel		Scratch/Scuff <75mm Paint Damage						251	394	
		Scratch/Scuff - Medium 75-150mm						515	810	
		Scratch/Scuff - Large 150mm+						724	1136	
		Dent - Small 25-75mm						290	432	
		Dent - Medium 75-150mm						592	887	
		Dent - Large 150mm+						839	1251	
Rear Sliding Door		Scratch/Scuff <75mm Paint Damage		411				353	417	
		Scratch/Scuff - Medium 75-150mm		737				669	842	
		Scratch/Scuff - Large 150mm+		989				910	1179	
		Dent - Small 25-75mm		450				392	456	
		Dent - Medium 75-150mm		814				746	919	
		Dent - Large 150mm+		1104				1025	1294	
Rear	Rear Badge	Broken/Damaged/Missing	53	46	79	97	28	36	29	
	Boot lock	Broken/Damaged/Missing	79	95	99	87	106	275	238	



Light Damage Charges Schedule

Area	Element	Type and Condition	CARS					VANS	
			Small	Medium	Intermediate	Large	Premium	Small Van	Van
	Tailgate/Boot Lid	Scratch/Scuff <75mm Paint Damage	237	251	270	261	242	299	438
		Scratch/Scuff - Medium 75-150mm	338	356	381	366	298	433	601
		Scratch/Scuff - Large 150mm+	383	405	426	413	304	497	657
		Dent - Small 25-75mm	275	289	309	300	280	338	476
		Dent - Medium 75-150mm	415	433	458	443	375	510	678
		Dent - Large 150mm+	498	520	541	528	419	613	772
	Rear Bumper	Scratch/Scuff <75mm Paint Damage	258	282	268	251	247	295	216
		Scratch/Scuff - Medium 75-150mm	343	382	370	339	337	419	296
		Scratch/Scuff - Large 150mm+	343	397	370	339	333	419	296
		Dent - Small 25-75mm	297	321	307	289	285	333	255
		Dent - Medium 75-150mm	420	459	447	416	414	496	373
		Dent - Large 150mm+	459	512	485	455	449	535	412
	Rear Fog Lamp (Right/Left)	Broken/Damaged/Missing	98	87	57	44		52	
	Rear Light (Right/Left)	Broken/Damaged/Missing	100	132	213	201	197	118	138
	Rear plate light	Broken/Damaged/Missing	38	43	73	55	38	34	24
	Rear Spoiler	Scratch/Scuff <75mm Paint Damage	147	185	184	183	176		
		Scratch/Scuff - Medium 75-150mm	212	256	261	267	247		
		Scratch/Scuff - Large 150mm+	212	256	273	267	218		
		Dent - Small 25-75mm	185	224	222	221	214		
		Dent - Medium 75-150mm	289	333	338	344	324		
		Dent - Large 150mm+	328	372	388	382	333		
	Rear valance	Scratch/Scuff <75mm Paint Damage	147	185	184	183	176		
		Scratch/Scuff - Medium 75-150mm	212	256	261	267	247		
		Scratch/Scuff - Large 150mm+	212	256	273	267	218		
		Dent - Small 25-75mm	185	224	222	221	214		
		Dent - Medium 75-150mm	289	333	338	344	324		
		Dent - Large 150mm+	328	372	388	382	333		
	Tow Eye Cover	Broken/Damaged/Missing	130	74	33	61	106	64	145
	Wiper Arm	Broken/Damaged/Missing	48	38	41	37	46	36	
	Wiper Blades	Broken/Damaged/Missing	36	23	22	28	43	30	28
	Rear Screen	Glass chip 5-10mm	35	35	35	35	35	35	35
	Number Plate	Broken/Damaged/Missing	25	25	25	25	25	25	25
	Rear Loading Door	Scratch/Scuff <75mm Paint Damage		246				276	284
		Scratch/Scuff - Medium 75-150mm		354				396	404
		Scratch/Scuff - Large 150mm+		403				453	463
		Dent - Small 25-75mm		285				314	322
		Dent - Medium 75-150mm		431				473	481
		Dent - Large 150mm+		519				569	579
	Step	Broken/Damaged/Missing					350	350	
	Tail-lift	Broken/Damaged/Missing					450	450	
Roof	Aerial	Broken/Damaged/Missing	13	77	95	114	215	23	23
	Roof	Scratch/Scuff <75mm Paint Damage	245	375	389	356	323	534	668
		Scratch/Scuff - Medium 75-150mm	350	537	564	507	415	781	980
		Scratch/Scuff - Large 150mm+	399	622	659	592	428	925	1166
		Dent - Small 25-75mm	283	414	428	395	361	573	707
		Dent - Medium 75-150mm	427	614	641	584	492	858	1057
		Dent - Large 150mm+	515	738	774	708	543	1041	1281
Interior	Boot Carpet	Broken/Damaged/Missing	129	182	158	273	160	314	529
	Bulkhead	Broken/Damaged/Missing	40	40	45	90	130	402	402
	Centre Console	Broken/Damaged/Missing	91	165	208	238	453	115	80
		Burn/Holed/Cut	65	65	65	65	65	65	65
	Door Panel	Burn/Holed/Cut	65	65	65	65	65	65	65
		Missing	233	288	323	364	598	183	234
	Front Left Seat Back Cover	Broken/Damaged/Missing	228	295	323	348	309	299	190
		Burn/Holed/Cut	65	65	65	65	65	65	65
	Front Left Seat Base Cover	Broken/Damaged/Missing	174	219	219	312	318	233	120
		Burn/Holed/Cut	65	65	65	65	65	65	65



Light Damage Charges Schedule

Area	Element	Type and Condition	CARS					VANS	
			Small	Medium	Intermediate	Large	Premium	Small Van	Van
	Front Right Seat Back Cover	Broken/Damaged/Missing	228	288	353	359	309	300	116
		Burn/Holed/Cut	65	65	65	65	65	65	65
	Front Right Seat Base Cover	Broken/Damaged/Missing	211	232	250	305	316	330	136
		Burn/Holed/Cut	65	65	65	65	65	65	65
	Gear Lever Gaiter	Broken/Damaged/Missing	111	61	68	53	108	117	46
		Burn/Holed/Cut	111	61	68	53	108	117	46
	Glove Compartment	Broken/Damaged/Missing	151	162	160	204	558	169	89
	Head Restraint	Broken/Damaged/Missing	146	116	308	159	160	151	151
	Interior Carpet	Burn/Holed/Cut	65	65	65	65	65	65	65
		Missing	303	578	671	564	833	729	717
	Interior Lighting	Broken/Damaged/Missing	42	109	117	176	344	33	57
	Key	Broken/Damaged/Missing	227	170	125	222	268	192	267
	Luggage Cover	Broken/Damaged/Missing	148	187	206	297	355	275	
	Rear View Mirror	Broken/Damaged/Missing	106	128	233	203	330	53	464
	Rear Armrest	Broken/Damaged/Missing			269	92	344	179	179
	Rear Left Seat Back Cover	Broken/Damaged/Missing	202	248	206	317	246	120	120
		Burn/Holed/Cut	65	65	65	65	65	65	65
	Rear Left Seat Base Cover	Broken/Damaged/Missing	268	517	370	228	46	207	532
		Burn/Holed/Cut	65	65	65	65	65	65	65
	Rear Right Seat Back Cover	Broken/Damaged/Missing	251	231	218	332	235	70	290
		Burn/Holed/Cut	65	65	65	65	65	65	65
	Rear Right Seat Base Cover	Broken/Damaged/Missing	198	371	255	218	57	134	440
		Burn/Holed/Cut	65	65	65	65	65	65	65
	Roof lining	Broken/Damaged/Missing	65	65	65	65	65	65	65
		Burn/Holed/Cut	65	65	65	65	65	65	65
	SD Card	Broken/Damaged/Missing	55	55	65	65	400		
	Speaker	Broken/Damaged/Missing	36	42	88	74	43	43	43
	Sunvisor	Broken/Damaged/Missing	36	66	98	92	52	68	68
		Burn/Holed/Cut	36	66	98	92	52	68	68
	Window Handle	Broken/Damaged/Missing	25					18	21
	Locking Wheel Bolt Key	Broken/Damaged/Missing	160	160	160	160	160	160	160
	Ply Lining	Broken/Damaged/Missing						155	155
Accessories	Tool Kit	Missing		24	85	19	9		35
	Hub Covers	Missing	27	29	22	23	23	17	19
		Scratch/Scuff <75mm Paint Damage	30	30	30	30	30	30	30
	Decals	Broken/Damaged	30	30	30	30	30	63	63
Missing		97	97	97	97	97	221	221	