



Light Damage Charges Schedule

Damage Area	Damaged Element	Type and Condition of Damage	CARS					VANS	
			Small	Medium	Intermediate	Premium	Large	Small Van	Van
Front	Badge	Broken/Damaged	51	67	80	63	68	63	76
		Missing	51	67	80	63	68	63	76
	Bonnet	Scratch/Scuff <75mm Paint Damage	231	278	305	365	265	255	227
		Scratch/Scuff - Medium 75-150mm	437	508	559	586	508	515	536
		Scratch/Scuff - Large 150mm+	584	665	734	705	687	705	781
		Dent - Small 25-75mm	231	278	305	365	265	255	227
		Dent - Medium 75-150mm	437	508	559	586	508	515	536
		Dent - Large 150mm+	584	665	734	705	687	705	781
	Bumper Moulding	Broken/Damaged	181	181	128	185	140	51	94
		Missing	181	181	128	185	140	51	94
	Bumper skirt	Broken/Damaged	68	99	62	58	132	84	77
		Missing	68	99	62	58	132	84	77
		Scuffed	68	99	62	58	132	84	77
	Front Bumper	Scratch/Scuff <75mm Paint Damage	234	251	226	237	250	216	199
		Scratch/Scuff - Medium 75-150mm	314	344	311	321	343	299	278
		Scratch/Scuff - Large 150mm+	314	344	311	321	343	302	403
		Dent - Small 25-75mm	234	251	226	237	250	216	199
		Dent - Medium 75-150mm	314	344	311	321	343	299	278
		Dent - Large 150mm+	314	344	311	321	343	302	403
	Fog Light (Right/Left)	Broken/Damaged	54	106	94		81		
		Missing	54	106	94		81		
	Front Grille	Broken/Damaged	164	205	204	263	251	211	163
		Missing	164	205	204	263	251	211	163
	Headlight (Right/Left)	Broken/Damaged	259	291	400	663	257	213	275
		Missing	259	291	400	663	257	213	275
	Indicator (Right/Left)	Broken/Damaged	25	14	19	26	13	28	14
		Missing	25	14	19	26	13	28	14
	Front Skirt (Right/Left)	Broken/Damaged	68	99	62	58	132	84	77
		Missing	68	99	62	58	132	84	77
	Tow Eye Cover	Broken/Damaged	121	124	85	97	115	21	29
		Missing	121	124	85	97	115	21	29
	Wiper Arm	Broken/Damaged	44	64	70	72	64	53	71
Missing		44	64	70	72	64	53	71	
Wiper Blades	Broken/Damaged	33	24	24	43	39	31	37	
	Missing	33	24	24	43	39	31	37	
Number Plate	Broken/Damaged	25	25	25	25	25	25	25	
	Missing	25	25	25	25	25	25	25	
Wind Screen	Glass chip 5-10mm	35	35	35	35	35	35	35	
Side (Right/Left)	Door (Front/Rear)	Scratch/Scuff <75mm Paint Damage	238	232	242	232	260	251	279
		Scratch/Scuff - Medium 75-150mm	450	437	465	400	501	506	608
		Scratch/Scuff - Large 150mm+	600	580	619	510	679	695	868
		Dent - Small 25-75mm	238	232	242	232	260	251	279
		Dent - Medium 75-150mm	450	437	465	400	501	506	608
		Dent - Large 150mm+	600	580	619	510	679	695	868
	Door Handle (Front/Rear)	Broken/Damaged	82	105	119	55	110	33	44
		Scratch/Scuff <75mm Paint Damage	154	152	150	110	152	210	121
	Door Seal (Front/Rear)	Broken/Damaged	126	69	69	129	91	70	63
	Front Wing	Scratch/Scuff <75mm Paint Damage	160	163	174	178	172	174	175
		Scratch/Scuff - Medium 75-150mm	328	335	362	318	370	390	452
		Scratch/Scuff - Large 150mm+	455	455	495	422	524	558	683
		Dent - Small 25-75mm	160	163	174	178	172	174	175
		Dent - Medium 75-150mm	328	335	362	318	370	390	452
		Dent - Large 150mm+	455	455	495	422	524	558	683
	Fuel Flap	Broken/Damaged	173	167	191	87	165	152	164
		Scratch/Scuff <75mm Paint Damage	123	124	127	128	117	124	124
	Side Indicator Repeater	Broken/Damaged	23	17	19	22	30	22	16
		Missing	23	17	19	22	30	22	16
	Door Mirror Glass	Broken/Damaged	37	51	49	217	48	41	32
		Missing	37	51	49	217	48	41	32
	Mirror Housing	Scratch/Scuff <75mm Paint Damage	106	140	145	199	135	128	135
		Broken/Damaged	118	207	206	192	159	132	148
		Missing	118	207	206	192	159	132	148
	Moulding (Front/Rear)	Broken/Damaged	242	298	376	520	293	172	221
		Missing	242	298	376	520	293	172	221
	Rear Wing	Scratch/Scuff <75mm Paint Damage	217	205	201	225	260	270	368
		Scratch/Scuff - Medium 75-150mm	418	380	403	382	490	541	761
		Scratch/Scuff - Large 150mm+	563	506	543	490	663	745	1028
		Dent - Small 25-75mm	217	205	201	225	260	270	368
		Dent - Medium 75-150mm	418	380	403	382	490	541	761
		Dent - Large 150mm+	563	506	543	490	663	745	1028
Pillar A	Scratch/Scuff <75mm Paint Damage	148	155	159	150	158	159	190	
	Scratch/Scuff - Medium 75-150mm	315	321	336	284	344	364	452	
	Scratch/Scuff - Large 150mm+	438	440	464	387	483	520	667	
	Dent - Small 25-75mm	148	155	159	150	158	159	190	
	Dent - Medium 75-150mm	315	321	336	284	344	364	452	
	Dent - Large 150mm+	438	440	464	387	483	520	667	
Pillar B	Scratch/Scuff <75mm Paint Damage	160	173	170	185	191	167	199	
	Scratch/Scuff - Medium 75-150mm	317	349	356	324	409	380	491	



Light Damage Charges Schedule

Damage Area	Damaged Element	Type and Condition of Damage	CARS				VANS		
			Small	Medium	Intermediate	Premium	Large	Small Van	Van
Front		Scratch/Scuff - Large 150mm+	424	474	486	427	584	543	733
		Dent - Small 25-75mm	160	173	170	185	191	167	199
		Dent - Medium 75-150mm	317	349	356	324	409	380	491
		Dent - Large 150mm+	424	474	486	427	584	543	733
	Pillar C	Scratch/Scuff <75mm Paint Damage						151	164
		Scratch/Scuff - Medium 75-150mm						292	164
		Scratch/Scuff - Large 150mm+						433	164
		Dent - Small 25-75mm						151	202
		Dent - Medium 75-150mm						292	241
	Pillar D	Dent - Large 150mm+						433	279
		Scratch/Scuff <75mm Paint Damage					158	181	148
		Scratch/Scuff - Medium 75-150mm					337	431	354
		Scratch/Scuff - Large 150mm+					512	633	539
		Dent - Small 25-75mm					158	181	148
	Sill	Dent - Medium 75-150mm					337	431	354
		Dent - Large 150mm+					512	633	539
		Scratch/Scuff <75mm Paint Damage	161	164	163	178	156	166	161
		Scratch/Scuff - Medium 75-150mm	231	234	236	250	220	238	225
		Scratch/Scuff - Large 150mm+	251	255	259	254	235	262	242
	Underside Protection	Dent - Small 25-75mm	161	164	163	178	156	166	161
Dent - Medium 75-150mm		231	234	236	250	220	238	225	
Dent - Large 150mm+		251	255	259	254	235	262	242	
Broken/Damaged		68	106	106	73	90	88	78	
Missing		68	106	106	73	90	88	78	
Wheel Trim (Front/Rear)	Broken/Damaged	64	77	63	78	78	44	54	
	Missing	64	77	63	78	78	44	54	
WingTrims	Missing	140	78	138	123	11	50	10	
Wheel Arch (Front/Rear)	Scratch/Scuff <75mm Paint Damage	71	75	91	59	90	78	70	
	Scratch/Scuff - Medium 75-150mm	71	76	125	59	90	78	70	
	Scratch/Scuff - Large 150mm+	71	77	158	59	90	78	70	
	Dent - Small 25-75mm	71	75	91	59	90	78	70	
	Dent - Medium 75-150mm	71	76	125	59	90	78	70	
Door Glass (Front/Rear)	Dent - Large 150mm+	71	77	158	59	90	78	70	
	Glass chip 5-10mm	35	35	35	35	35	35	35	
Alloy/Steel Wheel (Front/Rear)	Scratch/Scuff <75mm Paint Damage	65	65	65	65	65	65	65	
Rear Sliding Door	Scratch/Scuff <75mm Paint Damage					441	289	407	
	Scratch/Scuff - Medium 75-150mm					768	571	804	
	Scratch/Scuff - Large 150mm+					996	778	1098	
	Dent - Small 25-75mm					441	289	407	
	Dent - Medium 75-150mm					768	571	804	
Rear	Rear Badge	Dent - Large 150mm+					996	778	1098
		Broken/Damaged	51	67	80	63	68	63	76
	Boot lock	Missing	51	67	80	63	68	63	76
		Broken/Damaged	68	81	82	86	47	199	132
	Tailgate/Boot Lid	Missing	68	81	82	86	47	199	132
		Scratch/Scuff <75mm Paint Damage	226	242	252	223	302	265	476
		Scratch/Scuff - Medium 75-150mm	428	454	472	427	560	544	865
		Scratch/Scuff - Large 150mm+	575	601	618	569	748	752	1122
		Dent - Small 25-75mm	226	242	252	223	302	265	476
	Rear Bumper	Dent - Medium 75-150mm	428	454	472	427	560	544	865
		Dent - Large 150mm+	575	601	618	569	748	752	1122
		Scratch/Scuff <75mm Paint Damage	228	250	203	251	268	212	272
		Scratch/Scuff - Medium 75-150mm	310	342	283	354	369	293	393
		Scratch/Scuff - Large 150mm+	310	359	283	356	369	293	393
	Rear Fog Lamp (Right/Left)	Dent - Small 25-75mm	228	250	203	251	268	212	272
		Dent - Medium 75-150mm	310	342	283	354	369	293	393
		Dent - Large 150mm+	310	359	283	356	369	293	393
		Broken/Damaged	140	65	47	52	77	52	73
		Missing	140	65	47	52	77	52	73
	Rear Light (Right/Left)	Broken/Damaged	100	129	183	199	147	114	134
Missing		100	129	183	199	147	114	134	
Rear plate light	Broken/Damaged	38	43	59	35	51	36	25	
	Missing	38	43	59	35	51	36	25	
Rear Spoiler	Scratch/Scuff <75mm Paint Damage	154	224	169	167	159			
	Scratch/Scuff - Medium 75-150mm	220	314	242	239	225			
	Scratch/Scuff - Large 150mm+	220	314	252	240	225			
	Dent - Small 25-75mm	154	224	169	167	159			
	Dent - Medium 75-150mm	220	314	242	239	225			
Rear valance	Dent - Large 150mm+	220	314	252	240	225			
	Scratch/Scuff <75mm Paint Damage	154	224	169	167	159			
	Scratch/Scuff - Medium 75-150mm	220	314	242	239	225			
	Scratch/Scuff - Large 150mm+	220	314	252	240	225			
	Dent - Small 25-75mm	154	224	169	167	159			
Tow Eye Cover	Dent - Medium 75-150mm	220	314	242	239	225			
	Dent - Large 150mm+	220	314	252	240	225			
Wiper Arm	Broken/Damaged	117	85	21	46	121	14	16	
	Missing	117	85	21	46	121	14	16	



Light Damage Charges Schedule

Damage Area	Damaged Element	Type and Condition of Damage	CARS				VANS			
			Small	Medium	Intermediate	Premium	Large	Small Van	Van	
	Wiper Blades	Missing	41	41	41	71	38	49	71	
		Broken/Damaged	33	24	24	43	39	31	37	
		Missing	33	24	24	43	39	31	37	
	Rear Screen	Glass chip 5-10mm	35	35	35	35	35	35	35	
	Number Plate	Broken/Damaged	25	25	25	25	25	25	25	
		Missing	25	25	25	25	25	25	25	
	Rear Loading Door	Scratch/Scuff <75mm Paint Damage	Scratch/Scuff - Medium 75-150mm					375	383	425
			Scratch/Scuff - Large 150mm+				556	572	626	
			Dent - Small 25-75mm				654	665	734	
			Dent - Medium 75-150mm				375	383	425	
			Dent - Large 150mm+				556	572	626	
	Step	Broken/Damaged					654	665	734	
		Missing						350	350	
	Tail-lift	Broken/Damaged						450	450	
		Missing						450	450	
Roof	Aerial	Broken/Damaged	15	71	104	193	62	28	23	
		Missing	15	71	104	193	62	28	23	
	Roof	Scratch/Scuff <75mm Paint Damage	Scratch/Scuff - Medium 75-150mm	223	362	366	354	491	484	633
			Scratch/Scuff - Large 150mm+	324	533	546	477	712	723	947
			Dent - Small 25-75mm	365	613	633	500	816	845	1112
			Dent - Medium 75-150mm	223	362	366	354	491	484	633
			Dent - Large 150mm+	324	533	546	477	712	723	947
	Sunroof/Panoramic Glass R	Glass chip 5-10mm	365	613	633	500	816	845	1112	
			35	35	35	35	35	35	35	
	Interior	Air compressor	Broken/Damaged	43	43	92	202	95	42	42
Missing			43	43	92	202	95	42	42	
Boot Carpet		Broken/Damaged	113	179	152	137	380			
		Missing	113	179	152	137	380			
Bulkhead		Broken/Damaged	40	40	45	130	90	402	402	
		Missing	40	40	45	130	90	402	402	
Centre Console		Broken/Damaged	81	181	224	438	86	85	83	
		Burn/Holed/Cut	81	181	224	438	86	85	83	
		Missing	81	181	224	438	86	85	83	
Door Panel		Burn/Holed/Cut	242	287	376	520	293	171	221	
		Missing	242	298	376	520	293	171	221	
Front Armrest		Broken/Damaged			90	216		160	160	
		Missing			90	216		160	160	
Front Left Seat Back Cover		Broken/Damaged	262	268	355	306	350	218	187	
		Burn/Holed/Cut	262	268	355	306	350	218	187	
		Missing	262	268	355	306	350	218	187	
Front Left Seat Base Cover		Broken/Damaged	166	198	236	314	294	191	170	
		Burn/Holed/Cut	166	198	236	314	294	191	170	
		Missing	166	198	236	314	294	191	170	
Front Right Seat Back Cove		Broken/Damaged	262	274	328	306	339	206	119	
		Burn/Holed/Cut	262	274	328	306	339	206	119	
		Missing	262	274	328	306	339	206	119	
Front Right Seat Base Cove		Broken/Damaged	186	197	250	674	300	241	185	
		Burn/Holed/Cut	186	197	250	674	300	241	185	
		Missing	186	197	250	674	300	241	185	
Gear Lever Gaiter		Broken/Damaged	244	61	54	83	37	118	238	
		Burn/Holed/Cut	244	61	54	83	37	118	238	
		Missing	244	61	54	83	37	118	238	
Glove Compartment		Broken/Damaged	139	160	166	492	140	159	93	
		Missing	139	160	166	492	140	159	93	
Head Restraint		Broken/Damaged	146	116	308	160	159	151	151	
		Missing	146	116	308	160	159	151	151	
Interior Carpet		Burn/Holed/Cut	446	490	528	473	587	436	326	
		Missing	446	490	528	473	587	436	326	
Interior Lighting		Broken/Damaged	36	112	87	308	97	54	32	
		Missing	36	112	87	308	97	54	32	
Key	Broken/Damaged	185	126	265	260	131	265	265		
	Missing	185	126	265	260	131	265	265		
Luggage Cover	Broken/Damaged	98	188	171	325	265	120			
	Missing	98	188	171	325	265	120			
Rear View Mirror	Broken/Damaged	84	111	90	291	203	100	455		
	Missing	84	111	90	291	203	100	455		
Rear Armrest	Broken/Damaged			269	344	92	179	179		
	Missing			269	344	92	179	179		
Rear Left Seat Back Cover	Broken/Damaged	185	218	209	223	322	133			
	Burn/Holed/Cut	185	218	209	223	322	133			
	Missing	185	218	209	223	322	133			
Rear Left Seat Base Cover	Broken/Damaged	232	255	342	351	351	207	485		
	Burn/Holed/Cut	232	255	342	351	351	207	485		
	Missing	232	255	342	351	351	207	485		
Rear Right Seat Back Cover	Broken/Damaged	180	234	232	214	312	74	256		
	Burn/Holed/Cut	180	234	232	214	312	74	256		
	Missing	180	234	232	214	312	74	256		



Light Damage Charges Schedule

Damage Area	Damaged Element	Type and Condition of Damage	CARS						VANS	
			Small	Medium	Intermediate	Premium	Large	Small Van	Van	
Rear Right Seat Base Cover	Broken/Damaged		181	210	239	351	326	134	390	
	Burn/Holed/Cut		181	210	239	351	326	134	390	
	Missing		181	210	239	351	326	134	390	
Roof lining	Broken/Damaged		182	581	484	801	756	292	170	
	Burn/Holed/Cut		182	581	484	801	756	292	170	
SD Card	Broken/Damaged		55	55	55	400	55			
	Missing		55	55	55	400	55			
Shelves	Broken/Damaged		56	61	63	427	234			
	Missing		56	61	63	427	234			
Spare Wheel	Broken/Damaged		109	113	119	147	84	77	90	
	Missing		109	113	119	147	84	77	90	
Speaker	Broken/Damaged		36	42	88	43	74	43	43	
	Missing		36	42	88	43	74	43	43	
Sunvisor	Broken/Damaged		36	66	98	52	92	68	68	
	Burn/Holed/Cut		36	66	98	52	92	68	68	
	Missing		36	66	98	52	92	68	68	
Switches & Controls	Broken/Damaged		104	163	170	195	467	148	148	
	Missing		104	163	170	195	467	148	148	
Window Handle	Broken/Damaged		23	17	20					
	Missing		23	17	20					
Locking Wheel Bolt Key	Broken/Damaged		30	30	52	58	53	58	58	
	Missing		30	30	52	58	53	58	58	
Full Valet Required	Broken/Damaged		60	60	60	60	60	60	60	
	Soiled		60	60	60	60	60	60	60	
Interior Cleaning	Broken/Damaged		35	35	35	35	35	35	35	
Ply Lining	Broken/Damaged							155	155	
	Missing							155	155	
Accessories	Tool Kit	Missing		24	52	11	29	13	29	
	Hub Covers	Missing	48	31	29	29	20	22	29	
		Scratch/Scuff <75mm Paint Damage	30	30	30	30	30	30	30	
	Child Seat	Broken/Damaged	40	40	40	40	40	40	40	
		Soiled	40	40	40	40	40	40	40	